

HOT WORK SAFETY



The goal of a “HOT WORK SAFETY” program is to protect you from hazards associated with hot work. Hot work includes:

Cutting & Grinding

Riveting

Brazing & Welding

Soldering & Torching

The following procedures will help prevent you from being injured while performing hot work.

1. Inspect cylinders and hot work equipment prior to every use.
2. Provide good ventilation.
3. Wear proper personal protective equipment.
4. Warn others in immediate work area that you will be performing hot work activities.
5. Make sure that cylinders are properly stored, handled and secured during operation.
6. Make sure that work area has been inspected to remove any other potential hazards.
7. Make sure that you are properly trained.
8. Keep combustible materials away from hot work area.
9. Make sure that a fire extinguisher is within 25 feet of area.

SAFETY IS AS SAFETY DOES